

March 31, 2010

**VIA EMAIL**

Dr. John Ahlemeyer  
Gavin School District 37  
25775 West Highway 134  
Ingleside, IL 60041

Dear Dr. Ahlemeyer,

On Monday, March 29, 2010 Boller Construction performed the wood truss repair work at Gavin Central School. The trusses that were repaired were as follow:

- **Module C:**  
Truss 19 – Repair of partial bottom chord fracture.
  
- **Module A:**  
Truss 93 – Repair of full bottom chord fracture.  
  
Truss 87 – Repair of partial bottom chord fracture.  
  
Truss 22 – Repair of horizontal checks and a series of juvenile wood partial fractures over a 10' length of a bottom chord member .  
  
Trusses 90, 94, and 96 – Repair wood splinter on vertical member of truss.

The repairs were based on the drawings provided by WJE. Jon Sufra from WJE, and Ralph Schmidt of Schmidt Engineering (representing the Lake County Region Office of Education) were present to witness and verify the repairs. The attached photos show the repair on each truss. While the repairs were being performed, I walked through the attic spaces and filled in low spots in the insulation.

Sincerely,

Ted Haug, AIA , LEED AP

Cc : Bob Boller  
Ralph Schmidt  
John Duntemann, WJE  
Jon Sfura, WJE  
Wayne Machnich